

Addendum 2

Scope of Work:

PCRP UNIT #3 LM6000 DEPOT MAINTENANCE,
BEARING, NOZZLES AND HPT BUCKET
INSPECTION AND SERVICE BULLETIN
IMPLEMENTATION

This addendum is to correct the Engine Serial Number.

Engine Serial Number is to change from 191-398 to Engine Serial Number 191-472.